

The assembly process is shown in 12 sequential steps:

- Step 1:** The hull is shown with the deck area marked. Components E05, B2, E29, E16, E17, E31, and E76 are labeled.
- Step 2:** Component E06 is added to the deck area.
- Step 3:** Component E07 is added to the deck area.
- Step 4:** Component E08 is added to the deck area.
- Step 5:** Component E09 is added to the deck area.
- Step 6:** Component E10 is added to the deck area.
- Step 7:** Component E11 is added to the deck area.
- Step 8:** Component E12 is added to the deck area.
- Step 9:** Component E13 is added to the deck area.
- Step 10:** Component E14 is added to the deck area.
- Step 11:** Component E15 is added to the deck area.
- Step 12:** The final completed deck structure is shown, with component E16 labeled.

